



V Karen Miller <miller@design2train.com>

Control management system

1 message

ustin@stingraypoolspace.com <justin@stingraypoolspace.com>
To: miller@design2train.com

Wed, Apr 17, 2019 at 8:55 AM

Hello Mrs. Miller,

Upon arrival the main pump would not turn off at the control panel outside. After troubleshooting I have determined that the main pump mechanical relay is stuck in the closed position and needs to be replaced, I determined this by bypassing the main pump mechanical relay and testing another pump on the same auxiliary but using its own relay and it works fine. There are no issues with the control board

Thank you,

Owner
Justin Ray
Justin@stingraypoolspace.com
Stingraypoolspace.com